

REPORT OF CHANNEL CONDITIONS 100 TO 400 FEET WIDE (ER 1130-2-3165)					PAGE 1 OF 1		
					DATE April 27, 2004		
TO: The Record				FROM: U.S. Army Corps of Engineers 26 Federal Plaza, ATTN: CENAN-OP-ST New York, NY 10278-0090			
NEW YORK HARBOR, NEW YORK: Tarrytown Harbor Condition Survey					MINIMUM DEPTHS IN CHANNEL ENTERING FROM SEAWARD		
NAME OF CHANNEL	DATE OF SURVEY	AUTHORIZED PROJECT			LEFT OUTSIDE QUARTER (feet)	MIDDLE HALF (feet)	RIGHT OUTSIDE QUARTER (feet)
		WIDTH (feet)	LENGTH (nmiles)	DEPTH (feet)			
Reach A (South Channel) 0.0 MI to .34 MI	Map 2576N 8 & 12 Apr 2004	150	.3	12	7.7	7.8	7.4
Reach B (Wharf) .34 MI to .72 MI	Map 2576N 8 & 12 Apr 2004	250	.33	12	6.7	6.9	2.6
Reach C (North Channel) .72 MI to 1.0 MI	Map 2576N 8 & 12 Apr 2004	150	.24	12	8.1	8.7	8.1
REMARKS: <ul style="list-style-type: none">All depths in MLWChannel length is in nautical milesThe entire channel is shoaled in except for a few pockets.							